

Tree Number	DBH	Species	Hazard Rating	House #	Street	Ft. to Street	Block	Lot	Hazards	Recommendations	Action
93	13	White Ash	5	near pull out	North Shore Rd	6	tree pic 8		hollow, leaning	remove dead limbs	REMOVED 2014
46	10	Sassafras	4		Cranberry Ledge Rd	2			dead and leaning toward rd	remove, corner of North Shore	
125	24	Sugar Maple	4	AF 3	Ghost Pony Rd	1			60% dead, lots of trunk	remove	
128	25	Shagbark Hickory	4	15	Ghost Pony Rd	3			dead trunk, somewhat solid	remove	
92	22	White Ash	4	near pull out	North Shore Rd	4			hollow, dead branches	remove	REMOVED 2014
176	15	Black Oak	4	AF 5	Rotundo at corner	1			dead	remove	REMOVED 2014
155	15	Red Maple	4	2	Sleepy Hollow Rd.	5			dead limbs, rotten trunk	remove	
33	17	?	4	betwn 22 and 24	Stony Brook Rd	10			mostly dead	remove	
24	18	Tulip Poplar	3	21	Acorn	5			hollow and dead limbs	remove	
215	20	Pignut Hickory	3	C.O. Johnson Park	along trail from soccer to baseball near last base				trunk hollow	remove	
12	7-15	Red Maple	3	67	Ash St.	5			holes in trunk	monitor, leaning towards road	
19	20	Maple	3	AF 56	Ash St.	10			dead tree	remove, slight lean towards road	REMOVED
26	28	?	3	next to 16	Ash St.	1			trunk rot	remove / monitor	
32	10	Black Cherry	3	end of	Avon	10			leaning toward shed /mobile home	remove	
293	17	Red Maple	3	Neil Gylling Park	behind backstop 1st base line				monitor trunk over bleacher 1st base	prune dead branches	
296	9	Red Maple	3	Neil Gylling Park	behind backstop 2 near 2 picnic				hollow/wood pecker holes	remove/monitor	
297	9	Red Maple	3	Neil Gylling Park	behind backstop 2 near 2 picnic				hollow/wood pecker holes	remove/monitor	
295	7	Red Maple	3	Neil Gylling Park	behind backstop 2 near ?				hollow, lots of rot, top partly dead	remove	
9	10	Ash?	3	AF 35	Belton St.	7			dead	monitor, leaning away	
30	15	Chestnut Oak	3	18	Briar Lane	10			dead	leaning toward house but should miss	
118	13	Red Maple	3	3	Brook Trail	<1			hollow	remove / monitor	
119	8	?	3	AF 2	Brook Trail	4			dead	remove	
42	17	Black Locust	3	AF 48	Brookwood Dr	1			trunk rot, missing bark	remove / monitor	
62	13	Beech	3	AF 6	Cabin Spring Trail	2			part topped,rot root sprouts	monitor	
282	12	Red Oak	3	12	Carpenter	10			dead	remove	
120	17	Red Maple	3	15	Colby	12			dead	will fall across driveway	
161	15	White Oak	3	8	Conrad Strasse	10			bark off, leaning toward house	monitor	
48	24	Black Oak	3	7	Cranberry Ledge Rd	15			dead	monitor, limbs have been pruned	
183	16	Black Oak	3	AF 48	Crescent Dr. North	8			dead	remove/monitor	
190	18	Shagbark Hickory	3	AF 2	Crescent Dr. North	2			dead top,trunk rot	monitor	
179	12	Norway Maple	3	30	Crescent Dr. South	10			dead	remove/monitor	
180	10	White Ash	3	AF 38	Crescent Dr. South	5			dead, ivy covered	remove/monitor	
181	16	Sugar Maple	3	41	Crescent Dr. South	2			90% dead	remove	
15	12	Red Maple	3		cmr River/Chestnut	5			dead limbs, hanging limbs	remove	
201	9	Hickory	3	AF 139	Deer Run	3			tree split near top	monitor	
57	26	Red Oak	3	8	Division	2			half dead	remove/monitor	
191	16	Sugar Maple	3	AF Deer Run	Forest Lake Dr.	10			dead top	monitor, adjacent to boat rental	
195	20	Oak	3	next to huge rock outcrop	Forest Lake Dr.	3			dead	remove	
196	15	Red Maple	3	AF 181	Forest Lake Dr.	5			dead, near hydrant	remove	
115	28	Tulip Poplar	3	6	Fox trail	12	pic 4		huge widow maker	monitor, possibly remove	
123	25	Sugar Maple	3	NA	Ghost Pony Rd	2			many dead limbs, fungus on trunk	monitor 100' from Tamarack	

126	22	Sugar Maple	3	AF 3	Ghost Pony Rd	12		dead limbs, major trunk damage	remove	
131	8	White Ash	3		Ghost Pony Rd	8		mostly dead, trunk damaged	monitor	
230	15	Black Cherry	3	158	Glenside Trail	2		dead limbs, leaning	remove/prune	
252	11	Black Birch	3	AF 184	Glenside Trail	5		dead, leaning toward road	remove	
255	14	Sugar Maple	3	166	Glenside Trail	6		dead limbs, leaning toward house	remove/monitor	
256	22	Sugar Maple	3	171	Glenside Trail	5		dead limbs	remove/monitor	
262	12	Hemlock	3	111?	Glenside Trail	6		dead	remove	
265	30	Red Maple	3	AF 72	Glenside Trail	2		dead limbs, rotten trunk	remove	
204	12	Black Birch	3	2	Harbor View	5		dead	remove	
205	18	Black Oak	3		wood house crn of Forest Lake Dr.					
271	12	White Oak	3	AF 22	Hemlock Lake Dr west	5		dead, leaning toward house	remove	
272	28	Red Maple	3	47	Lake Drive	3		dead tree	remove	
287	11	Chestnut Oak	3	212	Lake Drive	2		dead limbs, hollow trunk	remove/monitor	
290	12	White Ash	3		Lake corner of Drive+Lackawanna			dead	remove	
71	28	Red Oak	3	31	Laurel Trail	<1		lost several limbs, lost bark on trunk	monitor	
136	40	White Oak	3	21	Little Paint Way	8		large dead limbs	monitor, some trunk damage	
145	42	White Ash	3	11	Manu Tr	8		dead limbs, cavities in large branches	monitor, prune	
233	20/17/15	Red Maple	3		tennis ct lot Marine Terrace	6		dead limbs, trunk rot	remove/monitor	
27	27	Black Oak	3	AF 42	Mayne	10		trunk rot and dead limbs	remove/monitor, cavities, leaning over road	
238	14	Norway Maple	3	26	Mt. Heights Dr	5		dead limbs, damaged trunk	remove	
1	17	Black Birch	3	4	Newton Ave	5		dead, covered with bittersweet	remove / monitor	
72	12	Black Birch	3		North Shore Rd	10		hole in base	growing out of rock, east of Frenches Gr. Rd	
96	8&10	Red Maple	3	AF Laurel Cove	North Shore Rd	6		dead	remove	
101	8/8	Red Maple	3	AF Dennis Hill	North Shore Rd	6		dead	remove/monitor	
105	20	Red Maple	3	AF WeaverHouseCover d	North Shore Rd	8	pic 1 and 2	dead, hollow, may fall away from road	remove	
106	10	White Oak	3	100	North Shore Rd	2		dead, leaning towards road	remove	REMOVED 2 trees 2014
109	8	Sassafras	3	before 159	North Shore Rd	12	pic 3	leaning, rotten	monitor, AF big rock	
117	20	Tulip Poplar	3	117	North Shore Rd	12		dead, leaning twds boat, away fr rd	mailbox 3 Hickory Trail	
132	13	? Aspen	3	14	Old Indian Spring Rd	5		mostly dead, major woodpecker holes	remove	
247	12	Sugar Maple	3	1	Ranger Trail	10		dead limbs	remove	
248	24	Red Oak	3	2	Ranger Trail	10		dead limbs	prune	
249	12	Black Birch	3	11	Ranger Trail	10		chunks of trunk missing	remove	
278	40	Silver Maple	3		next to golf course pond Reis Ave	2		dead limbs, large cavity	remove/monitor	
6	16	Pignut Hickory	3	48	River Street	5		hollow, leaning	monitor, possibly remove	
139	34	Red Oak	3	2	Roger Dr	10		dead limbs	leaning toward house	
177	10	?	3	AF 25	Rotundo	7		dead, will likely fall away from road	remove	
82	16	Red Maple	3	AF 5	Sautaug Trail	4		dead	remove/monitor	
39	20	Red Maple	3		Shadybrook and corner of Brookwood	1		cavities, tree split	remove, 3 trunked tree	
149	13	Red Oak	3	AF 56A	Sleepy Hollow Rd.	5		dead	remove	

159	20	Sugar Maple	3	68	Sleepy Hollow Rd.	15 or more?		1 in 3 fell, 2 are rotten and leaning	monitor	
74	33	White Ash	3	betwn 36 and 38	South Shore Rd	15		rot, dead limbs	huge rock outcrop	
76	15	Red Oak	3		South Shore Rd	4		dead, leaning toward road	monitor, trunk solid, S side rd before Weasaug	
303	7	Birch	3	Neil Gylling Park	to right of grill			dead+ leaning	remove	
23	24	Red Maple	2	23	Adair	2		hollow	remove / monitor	
298	10-14-10	Red Maple	2	Neil Gylling Park	along river over picnic table			dead branches	monitor	
312	26	White Oak	2		along road			dead limbs	prune	
214	10	Red Maple	2	C.O. Johnson Park	along trail from soccer to baseball			trunk hollow	remove/monitor	REMOVED 2014
213	10	Red Maple	2	C.O. Johnson Park	along trail from soccer to baseball			tree hollow trunk damage	remove	REMOVED 2014
11	8	Red Maple	2	AF 70	Ash St.	5		dead	remove / monitor	
20	3-5	Red Maple	2	AF 56	Ash St.	4		dead tree	monitor	
22	10-10	Red Maple	2	AF 42	Ash St.	2		top is dead	remove / monitor	
225	12	Quaking Aspen	2	parking spot 2	Autumn Hill Park	11		hole in trunk	remove/monitor	
21	10	Birch	2	AF 3	Banker	2		dead tree	remove	
18	20	Norway Maple	2	37	Beech St.	10		dead limbs	monitor	
292	21	Red Oak	2	Neil Gylling Park	behind backstop			large dead branches	prune dead branches	
7	12	White Ash	2	next to 5	Belton St.	7		leaning, some rot	remove / monitor	
8	11	Red Maple	2	AF 35	Belton St.	5		hollow, dead limbs	remove / monitor	
88	20	Red Maple	2	3	Birch	5		hollow	monitor	
89	26	Red Oak	2	3	Birch	15		bulbous base	monitor	
52	18	Tulip Poplar	2	4	Birch Lane	6		bark peeling, some rot	monitor	
231	38	Scarlet Oak	2	49	Birch Parkway	1		dead limbs, rot in trunk	remove/monitor prune	
232	30	Sugar Maple	2	46	Birch Parkway	8		trunk rot	remove/monitor	
220	7	Scarlet Oak	2	5	Braemar Ct.	10		50% dead	monitor	
70	8	White Ash	2	13	Bridge Trail	<1		damaged trunk	monitor	
34	28	White Oak	2	5	Brookwood Dr	5		dead limbs	monitor / prune	
40	24	Black Locust	2	67	Brookwood Dr	1		tree with cavities	remove/monitor, poor crotch	
41	21	Red Maple	2	next to 49	Brookwood Dr	10		lost large limb, can see thru trunk	monitor, may fall away from road	
43	29	Black Locust	2	39	Brookwood Dr	1		woodpecker holes	monitor, possibly cut roots from curb	
44	21	White Oak	2	24	Brookwood Dr	10		bulbous trunk	monitor	
31	10	Tulip Poplar	2	AF 56	Brookwood Rd.	5		lost bark on trunk, dying	monitor	
217	11	White Ash	2	C.O. Johnson Park	btw tennis and baseball field			dying	remove/monitor	REMOVED 2014
218	6	White Ash	2	C.O. Johnson Park	btw tennis court and baseball parking lot			dead	remove	REMOVED 2014
219	6	Black Cherry	2	C.O. Johnson Park	btw tennis court and baseball parking lot			dead	remove	REMOVED 2014
2	13	Red Oak	2	8	Byram Ave	10		few dead branches	possibly prune, small	
61	10	Yellow Birch	2	AF 6	Cabin Spring Trail	6		stump sprouts, dead at trunk	monitor pic 6	
280	15	White Oak	2	corner of Partridge	Carpenter	2		many dead limbs	prune	
281	17	Red Oak	2	AF 7	Carpenter	2		many dead limbs	prune	
283	9	Black Birch	2	12	Carpenter	5		dead	remove/between rides	
223	22	White Oak	2	8	Catherine Terrace	15		hole in trunk	monitor	
294	6	Red Maple	2	Neil Gylling Park	centerfield left of school			hollow/damaged	remove	
25	10	White Ash	2	AF 18	Chestnut	2		dead	remove	
121	16	White Ash	2	15	Colby	10		dead limbs	monitor, trunk damage	
122	10	Red Maple	2	1	Colby	7		trunk damage	monitor	
162	13	White Ash	2	next to 8	Conrad Strasse	2		split bark on trunk	monitor	

160	23	Black Birch	2	corner of	Conrad Strasse & Sandy's Lane	6		trunk rot and leaning	monitor	
47	8	White Oak	2		Cranberry Ledge Rd	3		dead	remove, corner of North Shore	
49	18	White Ash	2		7 Cranberry Ledge Rd	<1		trunk damage	monitor	
54	26	Beech	2		Cranberry Ledge Rd	4		hollow	monitor, across from rock out crop	
50	14	Red Oak	2		23 Cranberry Ledge Rd(possibly waterloo)	2		hollow	monitor, next to stream across from st pk pull off	
182	24	Black Oak	2	AF 52	Crescent Dr. North	5		dead limbs	monitor	
184	18	Red Oak	2	AF 44	Crescent Dr. North	1		dead branches, trunk damage	monitor	
185	12	Red Maple	2	AF 36	Crescent Dr. North	10		dead branches, hole in trunk	monitor	
186	15	Aspen	2	AF 36	Crescent Dr. North	10		dead branches, hole in trunk	monitor	
187	14	Red Oak	2	13	Crescent Dr. North	6		dead limbs	monitor	
188	23	Shagbark Hickory	2	10	Crescent Dr. North	8		dead limbs	monitor	
189	15	White Ash	2	AF 4	Crescent Dr. North	6		trunk rot,dead limbs	monitor	
157	8	Red Maple	2	2?	Crows Nest Rd.	3		holes in trunk	monitor	
158	25	Black Oak	2	13	Crows Nest Rd.	5		hole in base,dead limbs	monitor	
200	15	Black Oak	2	AF 139	Deer Run	3		dead limbs	monitor	
202	14	Chestnut Oak	2	AF 139	Deer Run	2		numerous woodpecker holes	monitor	
203	15	Black Oak	2	AF 25	Deer Run	1		dead branches	monitor	
64	9	Chestnut Oak	2	AF 17	Dennis Hill Rd	10		dead limbs	monitor	
58	8	White Oak	2	8	Division	2		dead	remove/monitor	
226	11	Black Birch	2	4	Douglas Terrace	12		top dead	remove/monitor	
5	15	White Oak	2		Drain Way	7		leaning	monitor	
192	20	Red Oak	2	AF 107	Forest Lake Dr.	10		dead limbs	monitor	
193	16	Chestnut Oak	2	AF 206	Forest Lake Dr.	8		dead, also remove Ailanthus next to it	remove/monitor	
194	18	Sugar Maple	2	btw lake+mansion on bend	Forest Lake Dr.	2		90%dead	remove	
197	26	Red Oak	2	AF 169	Forest Lake Dr.	15		dead limbs	monitor	
198	24	Black Oak	2	AF 143	Forest Lake Dr.	1		dead limbs, leaning	monitor	
199	14	Hickory	2	AF 139	Forest Lake Dr.	12		trunk damage, dead limbs	monitor	
124	16	White Ash	2	AF 3	Ghost Pony Rd	1		bark peeling off, trunk rot	monitor	
127	30	Sugar Maple	2	3	Ghost Pony Rd	5		dead limbs	monitor	
129	5	White Ash?	2	25	Ghost Pony Rd	3		dead branches, trunk damaged	monitor	
130	10	Red Maple	2	25	Ghost Pony Rd	6		dead limbs	monitor	
229	19	Red Maple	2	71	Glenside Trail	10		dead limbs	remove/monitor prune	
250	25	Red Oak	2	198	Glenside Trail	2		trunk bark peeling	remove/monitor	
251	18	Sugar Maple	2	AF 194	Glenside Trail	5		dead limbs	remove/monitor	
254	26	White Ash	2	171	Glenside Trail	3		dead limbs	monitor, prune	
257	27	Red Oak	2	165	Glenside Trail	5		dead limbs	prune	
258	30	Red Oak	2	155	Glenside Trail	3		rotten trunk	monitor closely	
259	28	White Ash	2	142	Glenside Trail	2		dead limbs	prune	
260	22	Black Oak	2	AF 122	Glenside Trail	8		dead limbs	prune	
261	19	White Ash	2	AF 117	Glenside Trail	5		dead limbs	prune	
263	26	Red Oak	2	112	Glenside Trail	5		dead limbs	prune	
264	25	Red Oak	2	102	Glenside Trail	7		dead limbs	prune	
114	16	Black Birch	2		Hawthorne Trail	2		some rot	monitor, before Pathfinder Trail	
206	14	Red Oak	2	8	Hemlock	5		dead limbs	monitor	
208	20	Red Oak	2	AF 20	Hemlock	5		top dead	monitor	
209	9	Red Oak	2	AF 22	Hemlock	10		dead	monitor	
133	21	Red Oak	2	6	Indian Spring Rd	6		guy wire girdling, dead limbs	monitor	
134	12	Red Maple	2	AF 6	Indian Spring Rd	6		trunk cavity, dead limbs	monitor	
86	16	Red Maple	2	10	Johnson	2		poor branching, dead limbs	monitor	

269	25	Norway Maple	2	14	Lake Dr west	5		poor branching	monitor,hole	
270	28	Red Maple	2	15	Lake Dr west	3		dead limbs	prune	
273	22	Red Maple	2	55	Lake Drive	6		dead limbs, hollow trunk	monitor	
274	19	Red Maple	2	55	Lake Drive	5		dead limbs, hollow trunk	monitor	
275	11	Norway Maple	2	AF golf course	Lake Drive	6		topped + dead	remove	
276	26	White Pine	2	AF 125	Lake Drive	2		dead limbs	prune	
277	20	Red Maple	2	AF 127	Lake Drive	2		dead limbs	prune	
284	9	Red Maple	2	147	Lake Drive	10		dead	remove	
285	14	Bigtooth Aspen	2	175	Lake Drive	6		dead limbs	prune/remove	
286	12	Quaking Aspen	2	206	Lake Drive	2		dead limbs	monitor	
288	19	White Ash	2	222	Lake Drive	5		dead limbs	monitor/prune	
56	7	White Ash	2	AF 10	Lakeview	3		dead and hollow	remove/monitor	
113	10/10	Red Maple	2	AF 37	Landone Trail	8		dead	monitor	
51	16	White Oak	2	59	Ledge Rd	10		butt rut, leaning slightly	monitor	
135	20	Pitch Pine	2		Little Paint Way	3		trunk damage	monitor	
137	8	Red Maple	2	17	Little Paint Way	10		mostly dead	monitor	
143	12	Black Cherry	2	9	Little Paint Way	8		strong lean toward road,lots of vines	monitor	
144	25	Red Oak	2	1	Manu Tr	8		center trunk bad,leaning tow boat	monitor	
146	30	White Ash	2	13	Manu Tr	6		some trunk damage, shelf fungus hi up	monitor	
90	20	Red Maple	2	AF 11	Maple?	8		poor fork,fork dead,dead branches	monitor	
234	13	Red Maple	2	11	Marine Terrace	2		dead limbs, trunk rot	remove/monitor	
228	16	Tulip Poplar	2	10	Matthew Drive	10		top dead	monitor	
28	15	Red Maple	2	38	Mayne	10		trunk rot, epicormic branches	monitor	
69	16	White Oak	2	41	Meteor Trail	<1		trunk cut and damaged	monitor	
236	29	Red Maple	2	10	Mt. Heights Dr	7		dead limbs	monitor	
237	18	Catalpa	2	AF 16	Mt. View Terrace	5		dead limbs	monitor	
306	19	Pin Oak	2	Neil Gylling Park	near 1st baseline			dead limbs	prune,remove other trunk	
308	18	Pin Oak	2	Neil Gylling Park	near 3rd base (field 1)+stands			dead limbs	prune	
216	8	Aspen	2	C.O. Johnson Park	near bocce ct			dying	monitor	REMOVED 2014
299	10	Red Maple	2	Neil Gylling Park	near grill along water			2/3 branches dead	monitor	
300	6	Red Maple	2	Neil Gylling Park	near grill along water			top 3/4 branches dead	remove	
301	14	Oak	2	Neil Gylling Park	near swing set			dead branches	prune	
302	11	Oak	2	Neil Gylling Park	near swing set			dead branches	prune	
304	11	Amelanchier	2	Neil Gylling Park	near swing set			prune, dead limbs	prune	
305	30	Pin Oak	2	Neil Gylling Park	near/over restroom			dead limbs	prune	
3	22	Red Oak	2	11	Newton Ave	5		few dead branches	possibly prune	
65	15	Red Maple	2		North Cove Rd	6		dead betw Dennis Hill and Frenches	monitor, should fall away from rd	
91	9	Red Maple	2	corner 206,N side	North Shore Rd	6		tree dead	remove	
94	11	White Ash	2	near pull out	North Shore Rd	8		hollow	remove	
98	14	Yellow Birch	2	AF FrenchesGroveRd	North Shore Rd	7		hollow, should fall away from road	monitor	
100	23	Red Maple	2		North Shore Rd	6		split trunk, half dead	monitor, should fall away	
103	23	Black Oak	2	82	North Shore Rd	12		dead limbs, one hanging	prune, remove widow maker	
104	18	White Ash	2	90	North Shore Rd	12		dead limbs	corner of Cranberry Ledge Road	
107	12	Red Maple	2	AF lake and road	North Shore Rd	15		leaning, possibly hollow	monitor, nxt to pole7422BY just before Muchivo	
112	14	Black Birch	2	AF 140	North Shore Rd	6		dead, may fall away	monitor	
67	16	Red Maple	2		North Shore Trail	5		one stem dead, the other okay	monitor, behind blue house pic 7	
53	10	Red Maple	2	8	Oak Trail	6		hollow and leaning	monitor	

164	20	Black Oak	2	56	Old Stagecoach	3		rotten trunk, dead limbs	monitor	
165	12	Yellow Birch	2	AF 41	Old Stagecoach	7		dead limbs, trunk hole, leaning	monitor	
63	8-10	Hemlock	2		Overview Terrace	<1		dead	remove/monitor	
66	10	Black Birch	2		Parsons	8		dead	corner of Frenches Cove Rd	
116	26	Red Oak	2	11	Pathfinder	5		dead limbs	possibly prune	
147	22	White Oak	2	7	Peach Tree St.	10		some dead limbs	monitor	
85	20	Red Maple	2	12	Pierson	2		poor branching	monitor	
227	10	Red Maple	2	13	Race Trail Run South	6		top dead	monitor	
279	20	Chestnut Oak	2	AF golf course pond	Reis Ave	2		dead limbs	remove/prune	
266	26	White Oak	2	6	Richmond Rd	2		dead limbs	prune	
267	13	Quaking Aspen	2	19	Richmond Rd	2		dead limbs	monitor/prune	
268	40+	White Ash	2	22	Richmond Rd	8		dead limbs	monitor/prune	
307	6	Cherry	2	Neil Gylling Park	right field (field 2)			dead	remove	
4	10	Amelanchier	2	24	River Rd.	3		half dead	monitor, should fall away from road	
13	24	Aspen	2	AF Spring Brook	River Rd.	8		hollow trunk	monitor	
14	13	White Ash	2	57?	River Rd.	6		bad pruning by power co, leaning	monitor	
16	25	Pin Oak	2	AF 64	River Rd.	10		dead limbs	prune	
17	23	Red Oak	2	AF 50	River Rd.	10		dead limbs	prune	
138	29	White Oak	2	2	Roger Dr	2		dead branches/trunk swelling	monitor	
141	53	White Oak	2	9	Roger Dr	1		dead limbs	monitor	
83	14	White Ash	2	AF 4	Rose Marie Lane	2		trunk rot	monitor/leaning away from rd	
84	8	Sassafras	2	AF 10	Rose Marie Lane	3		dead	monitor	
68	25	Red Oak	2	5	Rose Trail	7		dead limbs, some trunk rot	monitor	
178	18	Black Oak	2	20	Rotundo	5		dead limbs	monitor	
163	23	White Oak	2	corner of	Sandy's Rd & Old Stagecoach	3		dead limbs, hole in trunk	monitor	
80	20	Beech	2		Sautaug	3		hollow	near S Shore Rd, behind picket fence	
81	17	White Oak	2	8	Sautaug in Y	2		dead	monitor	
37	7	Black Locust	2	corner of	Shadybrook and Brookwood	5		dead / dying	monitor	
38	25	Red Maple	2	corner of	Shadybrook and Brookwood	10		trunk cavities	monitor	
36	11	Black Locust	2	3	Shadybrook Rd	5		leaning over road	monitor	
171	28	Tulip Poplar	2	2	Sherwood Forest Dr.	10		large dead limbs, trunk rot	monitor	
172	12	Black Oak	2	AF 55	Sherwood Forest Dr.	8		dead limbs, hole in trunk	monitor	
173	8	Red Maple	2	42	Sherwood Forest Dr.	7		dead	monitor	
174	20	Red Oak	2	AF 25	Sherwood Forest Dr.	4		dead limbs	monitor	
175	17	Red Oak	2	13	Sherwood Forest Dr.	1		dead limbs, holes in trunks, root fungus	remove/monitor	
150	10	Aspen?	2	50	Sleepy Hollow Rd.	7		dead	monitor	
151	9	Aspen	2	46	Sleepy Hollow Rd.	10		dead	monitor	
152	27	White Ash	2	41	Sleepy Hollow Rd.	2		mostly dead, ivy covered	remove/monitor	
153	20	Chestnut Oak	2	30	Sleepy Hollow Rd.	2		dead limbs	monitor	
156	14	Oak	2	23	Sleepy Hollow Rd.	6		trunk rot	monitor	
73	31	White Ash	2	26	South Shore Rd	2		multiple dead limbs	monitor/prune	
75	25	Red Maple	2	AF 44	South Shore Rd	6		trunk rot, dead limbs	monitor	
79	9	Black Birch	2	AF 90	South Shore Rd	10		dead and leaning slightly	monitor/remove	
224	13	Basswood	2	AF EMS	Stonehedge Dr.	10		hole in trunk	monitor	
45	20	Red Maple	2	12	Stony Brook Rd	10		leaning (root possibly out)	remove / monitor closely	
222	10	White Pine	2	7	Susan Lane	10		dead	remove	
311		Alanthus	1	Neil Gylling Park	along parking lot			invasive species	remove Alanthus	
291	11	Red Maple	1	16	Bank St			damaged trunk	monitor	
87	17	Red Maple	1	13A	Birch	5		epicormic branching	monitor	

35	15	White Oak	1	13	Brookwood Dr	3		bulbous trunk	monitor	
253	17	Red Maple	1	179	Glenside Trail	5		lots of burls	monitor	
55	26	Red Oak	1	4	Katona Trail	1		rot and dead limbs	monitor	
212	10	Pignut Hickory	1	C.O. Johnson Park	left of driveway by soccer field	25		damage to trunk	monitor	
142	21	Red Maple	1	13	Little Paint Way	8		strange lean over rd	monitor	
95	18	White Oak	1	near pull out	North Shore Rd	15		leaning over road	monitor	
97	17	White Ash	1	near end of pond	North Shore Rd	7		decay	monitor	
99	8	White Ash	1		North Shore Rd	4		some rot	monitor, near Dennis Hill and Pitch Pine	
102	9	White Oak	1		North Shore Rd	6		possible lightning strike	monitor, just past speed limit sign	
108	10	Red Maple	1	before 159	North Shore Rd	12		strange fork and hollow up high	monitor, AF big rock	
111	20	Chestnut Oak	1	AF road rock	North Shore Road	3		leaning, dead limbs	monitor	
170	8	Red Maple	1		28 Old Stagecoach	5		mostly dead, trunk rot	monitor	
309	28	White Oak	1	Neil Gylling Park	over 3rd base bleachers			dead limbs	prune	
310	12	Red Oak	1	Neil Gylling Park	over shed			dead limbs	prune	
148	17	White Ash	1	8	Peach Tree St.	5		trunk damage, dead branches	monitor	
140	34	Sugar Maple	1	corner of	Roger and Cross Tr	5		trunk damage	monitor	
154	8	Pine	1	10	Sleepy Hollow Rd.	2		dead	monitor	
110	25	Red Oak	1	42, near cliff	Strawberry Point	10		dead branches, leaning	monitor, prune	
221	12	Red Maple	1	2	Susan Lane	15		trunk damage, some rot	monitor	
246	15	White Ash	4	behind fence of water park	Tomahawk Trail	5		dead tree	remove	
241	18	Norway Maple	3	224	Tomahawk Trail	10		dead limbs	remove	
242	14	Norway Maple	3	218	Tomahawk Trail	3		dead	remove	
244	28	Sugar Maple	3	158	Tomahawk Trail	5		dead limbs, holes in trunk	remove/monitor	
239	12	Norway Maple	2	AF last house	Tomahawk Trail	3		dying limbs	remove/monitor	
240	12	Norway Maple	2	AF last house	Tomahawk Trail	3		holes in trunk	remove/monitor	
243	20	Sugar Maple	2	186	Tomahawk Trail	10		dead limbs, fading canopy	remove/monitor	
245	30	White Ash	2	entrance of water park	Tomahawk Trail	1		dead limbs, holes in trunk	remove/monitor	
60	18	White Oak	1	AF	Tote Rd	3		whole in trunk	monitor pic 5	
59	10	Sassafras	3	AF 23	Tote Rd	2		leaning and rotten	monitor	
10	20	White Ash	2	AF 16	Union	5		hollow limbs	monitor, leaning away	
289	11	Quaking Aspen	3	150' from	V of Lake Rd near Lackawana	6		dead	remove	
77	11	White Oak	2	1	Weasaug Trail	4		mostly dead, leaning	monitor, in a line of dead trees	
78	12	Maple	2	5	Weasaug Trail	7		mostly dead	monitor	
235	14	Hemlock	2	court	West Shore Rd	8		dead	remove	
207	10	White Ash	3	crn of Hemlock+	Winding Way	3		bark on trunk missing	remove/monitor	
211	11	White Ash	3	43	Winding Way	5		dead/dead limbs, on other stump	remove/monitor	
316	18	Sugar Maple	3	57	Winding Way	2		dead limbs	monitor	
210	26	Red Oak	2	32	Winding Way	3		dead limbs, woodpecker holes	monitor	
313	20	White Ash	2	46	Winding Way	4		dead limbs	monitor	
314	14	White Ash	2	?	Winding Way	5	AF Deer Run	dead limbs	remove/monitor	
315	11	White Ash	2	51	Winding Way	1		dead	monitor (topped), just trunk	
169	24	Black Oak	3	3	Woodland	15		dead, leaning over trampoline	remove if in row	
166	11	Hickory	3	1	Woodland Rd.	7		rotten trunk, dead limbs	monitor other trunk fell	
167	12	Aspen	2	6	Woodland Rd.	7		dead	remove/monitor	
168	21	White Ash?	2	corner of	Woodland+Crescent Dr.	1		trunk rot, covered with poison ivy	monitor	
29	12-12	Black Locust	3	AF 18	Woods Edge	1		split and hollow	remove	

TREES ADDED AFTER FORESTER'S INITIAL INVENTORY--by citizen complaint or Township observation									
no info	no info	no info	no info	218 Lake Drive	no info		in danger of falling	resident wants removed	REMOVED 2014
no info	no info	no info	no info	North Shore Road and corner of Frenches Grove Road	no info		large hanging limb	Don O'Donohue complaint 973-703-3049	REMOVED 2014
no info	no info	no info	no info	AF 80 Tamarack Road	no info		3 maples + 1 ash dead		REMOVED 2014